


0+400

$W=0,38 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,00\text{m}^2$

$S_n=0,28\text{m}$




0+500

$W=0,34 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,04\text{m}^2$

$S_n=0,26\text{m}$



0+536,50

$W=0,20 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,00\text{m}^2$

$S_n=0,18\text{m}$

