


0+002,50

$W=0,36 \text{ m}^2$

$N=0,00 \text{ m}^2$

$S_w = 0,00 \text{ m}$

$S_n = 0,00 \text{ m}$




0+100

$W=0,80 \text{ m}^2$

$N=0,34 \text{ m}^2$

$S_w = 2,24 \text{ m}$

$S_n = 0,94 \text{ m}$




0+200

$W=0,00 \text{ m}^2$

$N=0,24 \text{ m}^2$

$S_w = 0,00 \text{ m}$

$S_n = 0,42 \text{ m}$



0+300

$W=0,36 \text{ m}^2$

$N=0,00 \text{ m}^2$

$S_w = 0,42 \text{ m}$

$S_n = 0,04 \text{ m}$

